

Waste Site Reclassification Form

0057078 0544096

Date Submitted: 1/29/2001	Operable Unit(s): 100-BC-1	Control Number: 2001-021
Originator: S.G. Weiss	Waste Site ID: 100-B-10	
Phone: 372-9495	Type of Reclassification Action: Rejected <input type="checkbox"/> Closed Out <input type="checkbox"/> No Action X	

This form documents agreement among the parties listed below authorizing classification of the subject unit as rejected, closed out, or no action and authorizing backfill of the site, if appropriate. Final removal from the NPL of no action or closed-out sites will occur at a future date.

Description of current waste site condition:

This spring, reported in 1949, no longer exists and the precise location is unknown. In preparation for a 1991 spring sampling study, the entire shoreline of the River in the 100 Areas was searched for springs. Three were found at the 100-BC Area, all upstream (about 700 meters [2,300 feet] of the estimated location of this spring. No springs were found at or near the River shoreline below the 116-B-11 Retention Basin.

RECEIVED
APR 30 2002
EDMC

Basis for reclassification:

This is not a site where wastes have been disposed or spilled, but was the location where groundwater contaminated from the 116-B-11 Retention Basin exited the riverbank. The 116-B-11 Retention Basin and underlying plumes from old spills have been remediated and closed out. The groundwater is a separate Operable Unit (100-BC-5); it and any associated remaining contaminants will be addressed as part of that project.

<u>P. Chris Smith</u> DOE Project Manager	<u>[Signature]</u> Signature	<u>4/4/02</u> Date
<u>NA</u> Ecology Project Manager	<u>[Signature]</u> Signature	<u>4-11-02</u> Date
<u>Dennis Faulk</u> EPA Project Manager	<u>[Signature]</u> Signature	<u>4-11-02</u> Date